

FIG. 1





FIG. 3

FIG. 4




FIG. 5




FIG. 6







FIG. 7

FIG. 8



9/22

FIG. 9



10330" 60E49860

FIG. 10




FIG. 11




FIG. 12




FIG. 13





FIG. 14

FIG. 15




FIG. 16





FIG. 17

FIG. 18




FIG. 19




FIG. 19

FIG. 20

URL

TROUBLE DB INPUT WINDOW

OCCURRENCE DATE ~ 404

TYPE OF APPARATUS ~ 401

SUBJECT ~ 403

SERIAL NUMBER S/N ~ 402

DEGREE OF URGENCY ~ 405


SYMPTOM ~ 406

REMEDY ~ 407

PROGRESS ~ 408


410 411 412

[LINK TO RESULT LIST DATABASE](#) [SOFTWARE LIBRARY](#) [OPERATION GUIDE](#)

FIG. 21

SEMICONDUCTOR DEVICE MANUFACTURING FLOW

FIG. 22



T05230" 60E49860